

CONDITION REPORT

TRAILER BOATS / TRAILER SAILERS

			Home Ph_	
oat Dealer				11.00
	ру		SignedDate	
		HO II I		
Make Berwida			Reg. No. LL1335 Construction	A1.
Check visual condition of: Keel, Strakes and Chines Rest of Bottom Area Welds Iransom Bow and Topside Deck/Cabin Windscreen Steering System Canopy/Storm Cover	Good Poor		Is Hull fitted with: Operative Engine Blower Gas Detector fitted Battery Isolation Switch Bilge Pump operational Are all Deck fittings secure Navigational lights operational	
Osmosis present				
Please note your general comments o	on the overall conditi	ion of the hull, speci	fically those items that require immediate attention:	
HULL	s in	5210	u querge	
cenditio				
	~			
	~			
19.41		Мото	R	
10.41	Yes No Yes No Yes No Yes No Yes No	Мото		