



Auto Detective

www.autodetective.com.au

0421 504 096

admin@autodetective.com.au

7 August 2017

Regarding Mercedes Benz 1987 420SEL REG: UKB 704 ODO: 285,166kms

I encountered this vehicle presenting with a no start condition. Upon installing a battery and cranking the vehicle over confirming the non start condition there was an audible sound coming from the fuel pump. I then checked for spark coming from the H/T leads and spark is evident in the vehicle. I removed the air cleaner and unscrewed the fuel line, no fuel was pumping out so I checked for a blockage in the fuel system with none evident.

Upon inspection the lift pump is operational but the high pressure fuel pump is not operational. A new fuel pump and fuel filter is required to make the car run.

Kind Regards,

Kym McGuinness