



# 10/2003 (CP) FORD BA XR6 UTILITY

## Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	10/2003
<b>Make:</b>	FORD
<b>Model:</b>	BA
<b>Variant:</b>	XR6
<b>Series:</b>	
<b>Body Type:</b>	UTILITY
<b>Engine Size:</b>	4 LITRE 6 CYLINDER
<b>Transmission:</b>	4 SPEED AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	TURBO PETROL
<b>Ext. Colour:</b>	BLUE DUCO
<b>Int. Colour:</b>	
<b>Doors:</b>	2
<b>Seats:</b>	2
<b>Drive Type:</b>	RWD



## Asset Identification

<b>Odometer:</b>	298,468kms SHOWING	<b>Rego:</b>	S388 AEN	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	6FPAAAJGCM3U37182	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>	1	<b>Books:</b>		<b>Service Books:</b>	

## Features

ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, TONNEAU COVER, TOW BAR, TUB LINER

**\*\*DEFECTED\*\***  
CRACKED WINDSCREEN  
(SUSPENSION, TYRES & MIRRORS HAVE BEEN ATTENDED TO)

KEY #2

## Condition

Location	Damage
FRONT BUMPER	SCRATCHES DENTS, INTERIOR TRIM DAMAGE